


One Larkin Center
Yonkers, New York 10701
Tel. 914 376-8100
Fax 914 376-8584
equezada@yonkerspublicschools.org

Dr. Edwin M. Quezada
Superintendent of Schools

DATE: August 27, 2019

TO: Rev. Steve Lopez, President
and Members of the Board of Education

FROM: Dr. Edwin M. Quezada 

RE: **Request for Emergency Declaration**
Yonkers Montessori Academy Pool Drain

I have approved the attached Request for Emergency Declaration from Executive Director John Carr. On August 18th, in response to reports of periodic flooding, an inspection revealed new cracks in the 8 inch ductile iron swimming pool drain house trap located in the closet of Room G54. This fitting cannot be repaired and must be replaced using outside forces available to handle this type of work.

It is desirable to have this done before school starts in order to properly maintain the pool without flooding classroom space. The level of difficulty and the timing of this task precludes this work being done with in-house forces. The Department has engaged Mengler Mechanical to accomplish this work at a price not to exceed \$20,000.00.

Thank you for your cooperation and consideration of this request.

EMQ:br

Att.

C: Dr. Andrea Coddett, Ms. RoseAnne Collins-Judon, Dr. Fenix Arias, Mr. John Carr, Mr. Lee Pavone, Mr. John Liszewski, Ms. Elizabeth Janocha, Mr. Tom Collich, Mr. John Becker, Ms. Connie DiMaggio, Mr. Minaz David



OFFICE OF THE
SUPERINTENDENT
RECEIVED

Innovation • Inspiration • Excellence for All

2019 AUG 23 A 11:42

One Larkin Center
Yonkers, New York 10701
Tel. 914 376-8008
jcarr@yonkerspublicschools.org

Dr. Edwin M. Quezada
Superintendent of Schools

Dr. Andrea Coddett
Deputy Superintendent of Schools

John P. Carr, P.E.
Executive Director
School Facilities Management

MEMORANDUM

DATE: August 22, 2019

TO: Edwin M. Quezada

FROM: John P. Carr

RE: REQUEST FOR EMERGENCY DECLARATION
Yonkers Montessori Academy Pool Drain

On August 18, in response to reports of periodic flooding an inspection revealed new cracks in the 8 inch ductile iron swimming pool drain house trap located in the closet of Room G54. This fitting cannot be repaired and must be replaced using outside forces available to handle this type of work.


It is desirable to have this done before school starts in order to properly maintain the pool without flooding classroom space. The level of difficulty and the timing of this task precludes this work being done with in-house forces.

The Department has engaged Mengler Mechanical to accomplish this work at a price not to exceed \$20,000.00.

Mengler Mechanical has an exemplary history with the District in low bid capital work and past emergency declarations.

Please indicate your approval/disapproval of this Emergency Declaration by signing below:

APPROVED:

 8/26/19
Dr. Edwin M. Quezada, Superintendent of Schools

DENIED:

Dr. Edwin M. Quezada, Superintendent of Schools

JPC/jc

cc: Dr. A. Coddett, J. Liszewski, T. Collich, L. Pavone, C. Dimaggio, J. Becker, M. David