



**COROCORD** 

605 West Howard Lane, Ste 101 Austin, TX 78753

KOMPAN, INC. \* 605 W Howard Lane Ste 101, Austin, TX 78753 \* Tel 1-800-426-9788 \* Fax 1-866-943-6254 \* www.kompan.com

Site Location: C015827 Date 10/10/18 Family School 32 **Expiration Date** 1 Montclair Place Proposal No. SP60233 Yonkers, 10710 Project Family School 32 **United States** Ship to State/Zip NY 10710 Customer Service Representative Daniel Fabian Sales Representative Jeff Stowe Payment Terms DEP50%&N30 Invoice-to: C015827 Ship-to: Family School 32 Family School 32 1 Montclair Place 1 Montclair Place Yonkers, NY 10710 Yonkers, NY 10710 United States United States Minaz David Minaz David

Qty.	ltem No.	Description	Unit Price	Retail Price	Net Price
1	SSS-10CFH PIP	Total PIP Cost/Installation 50/50 Poured in Place Rubber 4.5" Thick, 5838 Sq Ft. Includes Dumpster and Security	123,583.22	123,583.22	123,583.22
1	EC-PG40T6800	Total Tile Cost/Installation 24X24X2.5 Tile + Polyfoam Quad Blok Connector PlayGuard Reducer 48x8x2.5	-93,583.22	-93,583.22	-93,583.22
1	SITEWORK	Egrip III Adhesive Egrip III Adhesive Freight for Tiles Includes Credit for the Install (25,567.52) Cost that Kompan is covering for the change from the tile vs PIP	-20,200.00	-20,200.00	-20,200.00